




NOTES:

1. GUTTER PAN SHOULD HAVE NEGATIVE SLOPE TO DRAIN INTO POROUS PAVEMENT

DESIGN:	DATE: 7/25/17
DRAWN:	
REVISIONS	



ENGINEERING DEPARTMENT

POROUS PAVEMENT DETAIL WITH UNDERDRAIN

PLATE
NUMBER

ST-21